

Certificate of Analysis



SINCE 1985

Quality Controlled Through Analysis

10630 FALLSTONE RD. HOUSTON, TEXAS 77099
P.O. BOX 741905, HOUSTON, TEXAS 77274

TEL: (281) 495-2400
FAX: (281) 495-2410

CLIENT:	Cold Mix Manufacturing	REQUESTED BY:	Mr. Warren Day
SAMPLE:	Multiple Samples	REPORT DATE:	February 5, 2009
LABORATORY NO:	53812 R	PURCHASE ORDER NO:	Pending

TEST

RESULT

The three samples were extracted in accordance with EPA Method 1311, Toxicity Leaching Characteristic Procedure (TCLP) for a period of 18 hours. The extracts were then filtered with a 0.45-micrometer (µm) glass filter and extracted for Total Petroleum Hydrocarbons (TPH), Diesel Range Organics (DRO) by EPA Method 8015M.

The Green Patch sample (53812-01) did not contain any detectable hydrocarbons. We did see a small amount of hydrocarbons in the samples identified as Package Pavement (53812-02) and Perma Patch (53812-03).

<u>Lab No.</u>	<u>Sample ID</u>	<u>Total Petroleum Hydrocarbons (TPH), (DRO Range), E.P.A. 8015M, ppm</u>
53812-01	Green Patch	<0.10
53812-02	Package Pavement	0.84
53812-03	Perma Patch	0.80

Respectfully submitted,
FOR: TEXAS OILTECH LABORATORIES, L.P.

A. Phil Sorurbakhsh
Director of Laboratory Operations



These analyses, opinions or interpretations are based on material supplied by the client to whom, and for whose exclusive and confidential use this report is made. Texas Oiltech Laboratories, Inc. and its officers assume no responsibility and make no warranty for proper operations of any petroleum, oil, gas or any other material in connection with which this report is used or relied on.

Quality Management System Certified to ISO 9001:2000



Cert. No. 5085